



Software Version: v1.2.15

ZincBlue2

Date: 10 March 2023

Document Number: SRN1551

Introduction

Version 1.2.15 contains important ZincBlue2 UPS firmware updates pertinent to the Inverter Locked Out issue and Inverter Out of Spec warning as well as updates to battery string management. Econolite highly recommends updating units in the field with this version.

This release includes changes provided in beta version v.1.2.14.

Firmware and Software

UPS Firmware v1.2.15 Release Notes

ZincBlue2 UPS 1000W/1500W

Performance Enhancements

- Reduced the chance of INVERTER LOCKED OUT errors reported to the system log.
- Removed the “INVTR OUT OF SPEC WARN” message from the system.
- The 500W Battery Panel, Module, and XRT are now still available to provide backup power even when the UPS-1000/1500 has an INVERTER LOCKED OUT occurrence.
- Updated revision number to 1.2.15

ZincBlue2 Battery 500W

Performance Enhancements

- Battery now recovers after shutdown due to low voltage cutoff.
- Enhanced battery string management.
- Updated revision number to 1.2.15

ZincBlue2 XRT Battery 3600W IMS

Performance Enhancements

- Enhanced battery string management.
- Updated revision number to 1.2.15

ZincBlue2 Software

Updated revision number to 1.2.15





Software Version: v1.2.15

ZincBlue2

Date: 10 March 2023

Document Number: SRN1551

Where to Download

The firmware and software update package is available on the Econolite One Stop Shop site at www.econolite/support under Product Resource Library in the Cabinets section.

For assistance, contact your Econolite Field Service Representative or Econolite Technical Support at: 1-800-225-6480, +1-714-630-3700.