Software Version: v1.2.13

ZincBlue2

Date: 29 March 2022

Document Number: SRN1530

Introduction

Version 1.2.13 contains ZincBlue2 UPS firmware updates for network related configuration enhancements, and convenience in viewing the system Serial Number on the Front Panel. This version also contains some performance improvements, and minor bug fixes.

This release includes changes provided in limited release versions v.1.2.11 and v1.2.12. These changes appear the end of this document.

Firmware and Software

UPS Firmware v1.2.13 Release Notes

ZincBlue2 UPS 1000W/1500W

Revision number change to 1.2.13

Enhancements

- The complete network configuration now appears on the LCD Network screen.
- Network Configurations can now be modified on the LCD screen by using the Navigation dial to select Network, then select Network Configuration.
- Web server optimization improves web application performance.
- ZincBlue2 UPS 1000W/1500W serial number now appears on the LCD screen.

ZincBlue2 Battery 500W

Revision number change to 1.2.13

ZincBlue2 XRT Battery 3600W IMS

Revision number change to 1.2.13

Bug Fix

- The battery bus is no longer enabled when XRT is in an error state.

![ECONOLITE]

Software Version: v1.2.13

ZincBlue2

Date: 29 March 2022

Document Number: SRN1530

ZincBlue2 Software

Revision number change to 1.2.13

Enhancements

- Increase performance through better web artifact caching.
- Simplify time selection dialog.

UPS Firmware v1.2.12 Release Notes (Limited Release version)

ZincBlue2 UPS 1000W/1500W

Revision number change to 1.2.12

Enhancements

- Web server optimization improves web application performance.

UPS Battery 500W

Revision number change to 1.2.12

ZincBlue2 XRT Battery 3600W IMS

Revision number change to 1.2.12

ZincBlue2 Software

Revision number change to 1.2.12

Enhancements

- Increase performance through better web artifact caching.
- Simplify time selection dialog.

Software Version: v1.2.13

ZincBlue2

Date: 29 March 2022

Document Number: SRN1530

UPS Firmware v1.2.11 Release Notes (Limited Release version)

ZincBlue2 UPS 1000W/1500W

Revision number change to 1.2.11

Bug Fix

- TCP_LISTEN_BACKLOG is enabled to prevent unnecessary TCP resets.
- Network socket is now closed before a reset due to firmware updates or network configuration changes.
- Power-Fail + Delay trigger no longer fires prematurely.

ZincBlue2 Battery 500W

Revision number change to 1.2.11

ZincBlue2 XRT Battery 3600W IMS

Revision number change to 1.2.11

ZincBlue2 Software

Revision number change to 1.2.11

Where to Download

The firmware and software update package is available on the Econolite One Stop Shop site at www.econolite/support under Product Resource Library in the Cabinets section.

For assistance, contact your Econolite Field Service Representative or Econolite Technical Support at: 1-800-225-6480, +1-714-630-3700.